Date: •

Thursday, 02/04/2009 2:25:06 PM

Úser:

Julie Dawson

## **Process Sheet**

Customer Job Number : CU-DAR001 Dart Helicopters Services

S.O. No. :

: 46829

**Estimate Number** 

: 13820

P.O. Number This Issue

: 02/04/2009

: NC

: LARGE FAB ASSY Type

**Part Number** 

**Due Date** 

**Drawing Name** 

: D22527 : D2252 REV G

**Drawing Number** 

: N/A : G

: FRAME

Project Number **Drawing Revision** 

Material

: 14/04/2009

Qty:

7 Um:

Each

Written By

Comment

Prsht Rev.

First Issue

Previous Run

Checked & Approved By

: Est Rev:A

09.03.18

New Issue EC verified by:DD

**Additional Product** 

Job Number:



Seq. #:

1.0

Machine Or Operation:

Description:

LARGE FABRICATION RESOURCE 1

304 SQ Tube .75x.75x.065W

M304TS0750W065

Scrap 1,5 fs

Comment: Qty.:

2.1000 f(s)/Unit Total: 14.7000 f(s)

batch:

304 SQ Tube .75x.75x.065W m111148

2.0

LARGE FAB 1

Comment: LARGE FABRICATION RESOURCE 1

1- Cut as per dwg D2252

2- Deburr and remove identification markings on tube

3.0

QC5

INSPECT WORK TO CURRENT STEP



Comment: INSPECT WORK TO CURRENT STEP

PACKAGING RESOURCE #1



09-04-07

4,0

PACKAGING 1

Comment: PACKAGING RESOURCE #1

Identify and Stock Location: 4)A

FINAL INSPECTION/W/O RELEASE

5.0

QC21





Comment: FINAL INSPECTION/W/O RELEASE


Job Completion



Dart	Δ۵	rne	ena	6	l td
Dail	ME	I U:	sua	CE	Lu

W/O:		ę	WO	RK ORDER CHANG	ES					
DATE	STEP	PR	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector			
Part No	:	PAR #:	Fault Categ	ory:	NCR: Yes	No <b>DQ</b>	\ <u>.</u>	Date:		
							A: N/C Closed: Date:			
NCR:			WORK ORDE	R NON-CONFORM	ANCE (NCR	3)				
DATE	STEP	Description of NC Section A	Initial Action Description Chief Eng Chief Eng		ion B Sign & Date	Verification Section C		Approval Chief Eng	Approval QC Inspector	
							,			
							<del></del>			

NOTE: Date & initial all entries



D

